



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Cofe

IN RE PATENT APPLICATION OF:

Our File: 29-34 US

Serial No: 10/715,165

Group: 2811

Patent No: 6,906,353

Issued: June 14, 2005

Title: HIGH SPEED IMPLANTED VCSEL

April 26, 2006

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
MAY 04 2006
of Correction

Dear Sir:

We respectfully request the correction of errors as set out in the attached Certificate of Correction. It is our understanding that, since these errors occurred in the United States Patent and Trademark Office, no fee is required.

The Commissioner is hereby authorized to charge any fees which may be required, or credit any overpayment, to Deposit Account 50-1465.

Respectfully,

Neil Teitelbaum
Regn No: 38,793

Customer No: 24949

Teitelbaum & MacLean
Registered Patent Agents Limited
1187 Bank Street, Ste 201
Ottawa, Ontario, K1S 3X7
Canada

Tel: (613) 523 3784
Fax: (613) 523 6799
Email: nt@patents.org
www.patents.org

/ewg

MAY 04 2006

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO: 6,906,353

DATED: June 14, 2005

INVENTOR(S): Shieh et al

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In Col. 9, line 12, "produce" should read – provide --

In Col. 10, line 29, "retraction" should read – refraction --

MAILING ADDRESS OF SENDER:

PATENT NO. 6,906,353

Teitelbaum & MacLean
Registered Patent Agents Limited
1187 Bank Street, Ste 201
Ottawa, Ontario
Canada
K1S 3X7

Tel: (613) 523 3784
Fax: (613) 523 6799
Email: nt@patents.org
www.patents.org

Form PTO 1050

MAY 04 2006